

SWIT®

LED Panel Lights S-2110CA / S-2110CS

Ver:A

USER MANUAL

SWIT Electronics Co.,Ltd.

Tel:+86-25-85805753
Fax:+86-25-85805296
http://www.swit.cc
E-mail: contact@swit.cc

Thank you for choosing SWIT products. Please read the instructions before using, and keep it for future reference.

Characteristics

- ◆ 576pcs of ultra bright LEDs, 50,000hrs long life time
- ◆ Max luminance: 1500Lux (3200K), 1600Lux (5600K) at 1m distance; 10%-100% flick-free dimming
- ◆ 3200K to 5600K continuously adjustable color temperature
- ◆ LCD touch screen, display and adjust color temperature and brightness dimming
- ◆ Powered by V-lock battery (S-2110CS)/Gold mount battery (S-2110CA), or AC-DC adapter
- ◆ Heat-free technology and constant current circuit design ensure consistent, stable, and accurate light output in various environments
- ◆ Designed for professional videography and photography

Cautions

1. Never disassemble the light or touch its inside with metal objects to avoid damage.
2. Never solder the LED bulbs by non-professionals
3. Never block the louvers; otherwise LED lighting effect and lifetime will be greatly reduced
4. Only use the provided adapter to avoid damage.
5. Never crash the LED touch screen with great force to avoid damage.
6. Only use the light in the temperature range of -10°C~40°C.

Specifications


MODEL LED	S-2110CA	S-2110CS
LED	576pcs of ultra bright LEDs	
Luminance	3200K: 1500Lux/m 5600K: 1600Lux/m	
Beam angle	60°	
Color temperature	3200K-5600K continuously adjustable	
Power	≤40W	
Working voltage	DC 11-17V, 4-pin XLR socket	
External power	Gold mount plate	V-mount plate
Dimension	403(W)×300(H)×95(D)mm	
Weight	1.9kg	
Accessories	Diffuser, U-shape bracket, AC adapter, power cord	

Packing List


	Packing details	Quantity
1	S-2110CS/S-2110CA	× 1
2	Diffuser	× 1
3	U-shape bracket	× 1
4	Power adapter	× 1
5	Power cable	× 1

Front and rear view

Front view:



Rear view:



1. Lock catch for the diffuser
2. U-shape bracket
3. Gold mount/V-mount battery plate
4. CT dimming knob
5. Brightness dimming knob
6. Power switch
7. LCD touch screen
8. 4-pin XLR socket
9. Fastening screw

Operation instructions

1. Open the barn door, set up the U-shape bracket on the light stand or bracket, and then fasten it. Loosen the knobs on both sides of the U-shape bracket, and then fix the knobs after adjusting the lighting angle.
2. Power the light with the AC power adapter or corresponding battery, turn it on and then the light works.
3. The upper side of the LCD shows brightness. Press "↑", "↓" or rotate brightness dimming knob to adjust the brightness from 10%-100%.
4. The bottom side of the LCD shows color temperature. Press "↑", "↓" or rotate CT dimming knob to adjust the color temperature from 3200K-5600K.
5. The diffuser can be removed from the groove in front of the LED by pressing button 1.